

In Photos: Southern Ukraine's Waterways One Month After Kakhovka Dam Disaster

July 13, 2023

The destruction of the Kakhovka dam on Ukraine's Dnipro River one month ago has had devastating economic, environmental and human costs for Ukraine. The dam's collapse emptied a key water reservoir, flooded swathes of southern Ukraine and displaced tens of thousands of people and animals. At least 52 people were killed in the disaster. Over one month later, the impacts of the dam's collapse continue to be felt in Ukraine's Zaporizhzhia and Kherson regions. Here is a look at the ongoing aftermath of the dam collapse:



Alexei Konovalov / TASS

Original url:

<https://www.themoscowtimes.com/2023/07/13/in-photos-southern-ukraines-waterways-one-month-after-kakhovka-dam-disaster-a81828>